

ACC-HPS85-3

Accessory Kit - Metal Casing



- Metal Chassis & Cover.
- Insulator.
- Mounting Screws and Washers.
- Assembly Instructions.

ASSEMBLY INSTRUCTIONS



1. Before assembly ensure unit has been turned OFF for at least 10 minutes.
2. "A" denotes customer mounting holes threaded 6-32 (8 nos.).
Maximum penetration into customer mounting hole is 0.10 inch.
3. "B" denotes PSU fixing stand-offs. Use screws 6-32 x 0.25" (4 nos.)
4. "C" denotes case assembly points. Use screw CSK M3 x 6mm (4 nos.)

Note : When cover is fitted other than by the manufacturer, it is the user's responsibility to ensure that the requirement of the relevant safety agency or agencies are complied with.

ORDERING INFORMATION

Model : ACC-HPS85-3

MECHANICAL DETAILS



UNIT : INCH
GENERAL TOLERANCE : +/- 0.005
OVERALL SIZE WITH CHASSIS & COVER:
L5.000X B3.300XH2.000

SMX POWER

3005 Avenida Simi, Simi Valley, CA 93063
TEL: (805) 582-2804 FAX: (805) 582-2308
<http://www.smxpower.com>